03500.016230 <u>PATENT</u>

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

: Examiner: L. Liang

SADATOSHI NARAZAKI, ET AL.

: Group Art Unit: 2853

Appln. No.: 10/082,182

: Patent No.: US 6,926,380 B2

Filed: February 26, 2002

Issued: August 9, 2005

For: INK JET RECORDING APPARATUS )

PROVIDED WITH INTERRUPT CONTROL: Confirmation No.: 2431

CIRCUIT AND METHOD FOR

CONTROLLING RECORDING APPARATUS: October 5, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

The statutory fee of \$100.00 is being paid electronically. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson Attorney for Patentees Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

MAW/llp

DC\_MAIN 218902v1

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

US 6,926,380 B2 PATENT NO.

DATED August 9, 2005 :

Narazaki et al. Page 1 of 2 INVENTOR(S) :

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 1

Line 39, "referred to" should read --referred to as--.

#### COLUMN 2

Line 9, "from," should read --from--.

#### COLUMN 7

Line 56, "des ignates" should read --designates--.

#### COLUMN 11

Line 64, "is" should be deleted.

Line 65, "step S1." should read --step S11.--.

#### COLUMN 12

Line 28, "lever" should read --level--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone


(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/llp DC\_MAIN 218907

**PATENT NO.** US 6,926,380 B2

No. of add'l. copies @ 30¢ per page



# 

### UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 6,926,380 B2

**DATED** : August 9, 2005

INVENTOR(S): Narazaki et al. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 19

Line 45, "on/off" should read --ON/OFF--.

Line 48, "stop mode or halt" should read --STOP mode or HALT--.

Line 49, "on/off" should read --ON/OFF--.

Line 51, "stop" should read --STOP--, and "halt" should read --HALT--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,926,380 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/IIp DC\_MAIN 218907